

Message

From: Barnett, Thomas R [Thomas.Barnett@arcelormittal.com]
Sent: 3/28/2017 8:31:10 PM
To: Fitzgerald, Sean F MST1 [Sean.F.Fitzgerald@uscg.mil]; Beslow, Mike [beslow.mike@epa.gov]
CC: David Greinke (DGREINKE@idem.IN.gov) [DGREINKE@idem.IN.gov]; nream@idem.IN.gov
Subject: Outfall and sump report, Tuesday, March 28th, 2017
Attachments: img-328153330-0001.pdf

Today and tomorrow National is replacing the four foot beams that hold the rollers to the walls for the hard booms with 8 foot beams due to the large swings in Canal levels.

Thomas Barnett | Manager, Environmental Technology
ArcelorMittal Indiana Harbor LLC.
ArcelorMittal USA LLC

Environmental Department | 3001 Dickey Road, Sta. 001
East Chicago, IN 46312

T +219 399 2380 | M +219 313 1605 | F +219 399 3211 | www.arcelormittal.com

-----Original Message-----

From: WorkCentre 5225 [mailto:no-reply@arcelormittal.com]
Sent: Tuesday, March 28, 2017 3:34 PM
To: Barnett, Thomas R <Thomas.Barnett@arcelormittal.com>
Subject: Scan from a Xerox WorkCentre

Please open the attached document. It was scanned and sent to you using a Xerox WorkCentre.

Number of Images: 3
Attachment File Type: PDF

Device Name: WorkCentre 5225
Device Location:

For more information on Xerox products and solutions, please visit <http://www.xerox.com/>